

# POTH HILLE & CO. LIMITED

## SUGGESTED GUIDELINES FOR THE USE OF WARM AND CREAM SOFT DEPILATORY WAXES

1. Heat the wax to around 40°C by either:-
  - (a) Placing the jar in a suitable warm wax heater
  - (b) Emptying the wax directly into the heater
2. As an alternative the jar may be heated by being immersed in hot water making sure no water spills over into the wax.
3. When the wax reaches the required temperature (no hotter than 43°C), apply a thin layer in the direction of the hair growth with a depilatory wooden spatula. Do not cover too large an area at one time.
4. Place an epilation strip or equivalent over the waxed area, pressing firmly.
5. Pull the strip sharply against the direction of the hair growth whilst holding the surrounding skin.
6. Dispose of strip.
7. The waxed area of skin should then be treated with an after wax lotion.
8. Depilatory wax should not be used on damaged or sensitive skin.
9. No attempt should be made to re-use the strips or filter out used wax.

The above method of use is given purely as a guideline. This may be adapted to suit the requirements of individual users.